



Inbound as Received - Slim

BC_5810_Timber_Oaks_Ridge_Inbound_8.12.2026

Complete

Address, JP or ID

BC_5810_Timber_Oaks_Ridge_Inbo
und_8.12.2026

Corner gap creates inadequate support and increases the risk of corner movement, separation, or damage during handling and transportation.



Photo 1



Photo 2

Prepared by

BC_5810_Timber_Oaks_Ridge_Inbo
und_8.12.2026

Media summary



Photo 1



991

Prod. Date: 08/0

Packaging: FAC

Fin Loc.: DAL

AUM SDR

AUSTIN
SMOLDER
MAP
800 DOOR

B18 R

18" BASE 1 DR

B18 R

Ship To: BUILDER'S CHOICE
EDC MOVERS
2228 WIRTCREST LANE
SUITE A
HOUSTON TX 77055

PO 192234WC

Job **5810 TIMBER OAKS RIDGE**



Packaging Barcode

Frm:DA

Special Instructions 99143900800001

HINGE = 6-Way Adj SOL (6WS)
HINGE DIRECTION = HR

SHELF = 3/4 Shelf

DRAWER TYPE = 5/8 FB Slidemount (F)

OVERLAY = 5475

PACKSIZE TYPE = 7, DEPTH = 24, WIDTH = 18, HEIGHT = 34.5

Dr: 16 x 21 5/8 (Q:1)
Dwr: 16 x 5 1/2 (Q:1)

TSCA Title VI Compliant



Qua
1 o

Photo 2