



Cabinet Delivery

5919_Monte_Thomas_Dr

Complete

Flagged items	1
Address	5919_Monte_Thomas_Dr
Prepared by	William DAddio

Flagged items

1 flagged

Delivery

Cabinets were Carefully lowered to the floor for hand truck.
NEVER placed down on 1 single corner?

No

Minor Corner Integrity



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5