



Cabinet Delivery

BC_18019_Harmony_Delivery_7.20.2026

Complete

Actions	0
Address	BC_18019_Harmony_Delivery_7.20 .2026
Prepared by	William DAddio

Delivery

Job site ready to receive cabinets: RE - drywall in, Garage doors on, clear path to home.

N/A

Cabinets were Carefully lowered to the floor for hand truck. NEVER placed down on 1 single corner?

N/A

Hand Truck was CAREFULLY placed under cabinets and did not HIT any structure of cabinet?

N/A

Stacks in home were no more 84" tall, stable and kept from harm.

Yes

Good Stacks



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7




Photo 8



Photo 9



Photo 10



Photo 11



Photo 12



Photo 13



Photo 14



Photo 15




Photo 16




Photo 17



Photo 18



Photo 19



Photo 20



Photo 21



Photo 22

BOL left with cabinets with driver's legible signature.

N/A

Hard Hats on.

N/A

Truck Stayed On Pavement.

N/A