



Cabinet Delivery

BC_18027_Harmony_Delivery_7.20.2026

Complete

Address BC_18027_Harmony_Delivery_7.20.2026

Prepared by William DAddio

One Damaged other wise good stacks



Photo 1

Delivery

Job site ready to receive cabinets: RE - drywall in, Garage doors on, clear path to home.

N/A

Cabinets were Carefully lowered to the floor for hand truck. NEVER placed down on 1 single corner?

N/A

Hand Truck was CAREFULLY placed under cabinets and did not HIT any structure of cabinet?

N/A

Stacks in home were no more 84" tall, stable and kept from harm.

Yes



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7



Photo 8

BOL left with cabinets with driver's legible signature.

N/A

Hard Hats on.

N/A

Truck Stayed On Pavement.

N/A