



Cabinet Delivery

BC_6522_Lenwood_Ln

Complete

Score

2 / 2 (100%)

Address

BC_6522_Lenwood_Ln



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5

Prepared by

William DAddio

Delivery		2 / 2 (100%)
Job site ready to receive cabinets: RE - drywall in, Garage doors on, clear path to home.		Yes
Cabinets were Carefully lowered to the floor for hand truck. NEVER placed down on 1 single corner?		N/A
Hand Truck was CAREFULLY placed under cabinets and did not HIT any structure of cabinet?		N/A
Stacks in home were no more 84" tall, stable and kept from harm.		Yes
BOL left with cabinets with driver's legible signature.		N/A
Hard Hats on.		N/A
Truck Stayed On Pavement.		N/A
Issues & Documentation		

Once this audit is complete, export a PDF report via the SafetyCulture app: tap the three-dot menu on the completed inspection and select 'Export as PDF'.