



Cabinet Inbound Builders Choice

William DAddio Complete

Score	1 / 2 (50%)	Actions	0
BC Address			2915 Cronus Way KB
Prepared by			William DAddio

Receiving Process

1 / 2 (50%)

Cabinet was properly secured / strapped during transport

Yes

Packaging In Tact and No Cabinet Damage

No




Photo 1



Photo 2



Photo 3

Delivery documentation (packing slip / BOL) was present and accurate

N/A

Delivery was received within the expected timeframe

N/A

Issues & Documentation

Once this audit is complete, export a PDF report via the SafetyCulture app: tap the three-dot menu on the completed inspection and select 'Export as PDF'.