



Site Assessment

BC_10742_Ursa_St_Job_Site_8.14.2026

Complete

Actions 0

Address BC_10742_Ursa_St_Job_Site_8.14.2026

Overall delivery condition HIGH-RISK to personel & product / not delivery-ready Garage Door Absent ~ No clear Path



Photo 1



Photo 2



Photo 3




Photo 4

Prepared by BC_10742_Ursa_St_Job_Site_8.14.2026

026

Media summary



Photo 1



Photo 2



Photo 3




Photo 4



Photo 5