



Staging

JP 80619830_Alondra

Complete

Score	2 / 4 (50%)
Address	JP 80619830_Alondra
Prepared by	William DAddio

Staging		2 / 4 (50%)
Cabinets were Carefully lowered to the floor for hand truck. NEVER placed down on 1 single corner?		N/A
Hand Truck was Carefully placed under cabinets & NOT "hitting" any product surface?		N/A
Stacks were under 8' tall, stable and kept from harm.		No
Product packaging compromised unable to to determine product integrity		
 		
Photo 1	Photo 2	
All pallets were in good service and nails are flush.		Yes
Shrink wrap did not compromise packaging or cabinet.		Yes